

**REPORT OF PERIODIC THOROUGH EXAMINATION
OF HOIST OR LIFT**

as required by the Lifting Operation and Lifting Equipment Regulations 1998;
or the Lifting Operations and Lifting Equipment Regulations (Northern Ireland) 1999;
or the Safety, Health and Welfare at Work (General Application) Regulations 2007 S.I. No. 299.

Policy: H9S086179

Plant Code: L27AHH

Previous Report: 220316-015-0027PL1

Site: 00001

Schedule: L0001

Report Number: 080916-001-0028EC1

LOL54

Employer (or owner) of premises	THE GALLEON LEISURE CENTRE
Address	99 Titchfield Street, Kilmarnock East Ayrshire, KA1 1QY
1. (a) Type of hoist or lift and identification number and description	Passenger/Goods Lift Hydraulic Thyssenkrupp Serial No.:- MJ0520 1986 - Refurbished 2011
(b) Date of construction or reconstruction (if ascertainable)	
2. (a) Is this the first thorough examination following installation of the equipment at the above site/location?	No
(b) Were examinations in accordance with an examination scheme?	No
3. Maintenance Are the following parts of the hoist or lift properly maintained and in good working order? If not, state what defects have been found or tests required to confirm continued safe use.	
(a) Enclosure of hoistway or liftway.	Yes
(b) Landing gates and cage gate(s).	Yes
(c) Interlocks on the landing gates and cage gate(s).	Yes
(d) Other gate fastenings.	No - Door hanger rollers showing wear - to be considered for replacement. Yes
(e) Cage or platform and fittings, cage guides, buffers, interior of hoistway or liftway.	Yes
(f) Over-running devices.	Yes
(g) Suspension ropes or chains, and their attachments.	Yes
(h) Safety gear, i.e. arrangements for preventing fall of platform or cage.	Visual examination only, not tested.
(j) Brakes.	N/a - Hydraulic System.
(k) Worm or spur gearing.	N/a - Hydraulic System.
(l) Other electrical equipment.	Shaft lights not illuminating.
(m) Other parts.	Ground floor door release to adjust.
4. What parts (if any) were inaccessible?	All internal mechanical and electrical parts.
5. Repairs, renewals, tests or alterations required to enable the hoist or lift to continue to be operated with safety (if none enter "None") :-	
(a) defects found which give rise to imminent danger and require attention immediately.	None
(b) defects found which could, in time, give rise to danger and require attention or tests required within the specified time period.	None
6. Maximum safe working load subject to repairs, renewals or alterations (if any) specified at 5.	630 kg/8 Persons
7. Other observations	See Plant Report Continuation


This is to certify that on the date of examination the hoist or lift was thoroughly examined and unless, otherwise indicated above, was safe to operate, and if the first examination following installation, was installed correctly.

Date of Examination: 07 Sep 2016

Date of Last Examination: 10 Mar 2016

Inspecting Engineer: Mr R Chambers

Date of Next Examination: 07 Mar 2017

Signature: 

Qualification: Engineer Surveyor

PLANT REPORT CONTINUATION



HSB Engineering Insurance

Policy: H9S086179

Plant Code: L27AHH

Previous Report: 220316-015-0027PL1-C01

Site: 00001

Schedule: L0001

Report Number: 080916-001-0028EC1

Occupier THE GALLEON LEISURE CENTRE

Address 99 Titchfield Street, Kilmarnock
East Ayrshire, KA1 1QY

PRC1

Section	Remarks
7	Lifting Beam (at shaft top): Safe working load = 1 Ton, Serial No.895 - no apparent defects. Controls and Hydraulic System refurbished 2011. Last recorded service: 09.08.2016.

Date of Examination: 07 Sep 2016

Inspecting Engineer: Mr R Chambers

Signature:

Date of Last Examination: 10 Mar 2016

Date of Next Examination: 07 Mar 2017

Qualification: Engineer Surveyor

HSB Engineering Insurance Services Limited
Registered in England and Wales: 03010292,
New London House, 6 London Street, London EC3R 7LP
Registered as a branch in Ireland: 906105
Telephone: 0845 345 5510

HSB Engineering Insurance Services Limited
is accredited by the United Kingdom
Accreditation Service

