## **Certificate of Inspection**

## **Alert Fire Scotland**

## **Invoice Address**

The Galleon Centre 99, Titchfield Street Kilmarnock



**Location Address** 

Alert Fire Scotland
The Old Coach House
Lochlibo Road
Burnhouse, Beith
Ayrshire
KA15 1LF

Certificate of Inspection and Conformity.

Fire Extinguishers Serviced to BS 5306 Part 3 and 8

Customers are obliged under Fire Safety Order 2005 and the Fire Safety (Scotland) regulations 2006 to provide an appropriate level of Fire Fighting Equipment at all times. Any nonconforming equipment should be replaced as soon as possible.

Provision of additional extinguishers to provide sufficient cover. Fire Points should be checked regularly ensuring equipment has not been discharged or damaged.

All Fire F	oints	should be	in the	appropriate	locations.

UANTITY	DESCRIPTION	Inspected	Non-conforming
25	2Kg Co2	23	
18	6Ltr Foams	18	
3	9Ltr Waters	3	
1	9Ltr Foam	1	
1	6Ltr Wet Chemical Foam	1	
1	2Ltr Foam	1 1	
3	Fire Blankets	3	
	Site equipment fully maintained to standard.		
	Minor non-conformance/no major equipment faults.		

**DIRECT ALL INQUIRIES TO:** 

Ray Cleland 07807 478 369

email: ray.alertfire@yahoo.co.uk

**Engineer: Ray Cleland** 

Signature Ray Cleland

F.E.T.A.. Accredited Engineers

**B.A.F.E.** Qualified



22/04/2016