PLANT INSPECTION REPORT





Policy: H9S086179

Previous Report: 230315-007-0025SB2

00001

Report Number: 220316-006-0027PL1

PIR1

Occupier THE GALLEON LEISURE CENTRE

Address

99 Titchfield Street, Kilmarnock East Ayrshire, KAl 1QY

Sched Pla io. Co		Item	Remarks	
30018 B04	1A10	Hot Water Storage Cylinder S.No.:FD11795253 Andrews SWP: 10.35 bar Max Locn.:Dry Sports, Plant Room	No apparent defects. Capacity: 454 litres Maximum working pressure: 10.35 bar	
0027 B04	AlO	Hot Water Storage Cylinder S.No.:LA33767425 Andrews SWP: 10.3 bar Max Locn.:Dry Sports Plant Room.	No apparent defects. Capacity: 454 litres	
5 B05.		S.No.:22386/1 Pullen Locn.:Dry Sports, Plant Room CHECKED 29-3-16	Visual examination with random ultrasomeasurements. Capacity: 60 litres Charge pressure: 4 bar Corrosion at top plug - to monitor. No other apparent defects.	MAINTE NANCE
0016 B05		Pressure Vessel S.No.:22386/2 Pullen Locn.:Dry Sports, Plant Room	Visual examination with random ultrasomeasurements - no apparent defects. Capacity: 60 litres Charge pressure: 4 bar	
0021 B37		Heat Exchanger (Plate type) S.No.:11156A UK Exchangers Ltd SWP: 6 bar Max	No apparent defects. Capacity: 4 litres/side. Working at: 2.0 bar.	
0022 B371		Heat Exchanger (Plate type) S.No.:11156B UK Exchangers Ltd SWP: 6 bar Max	No apparent defects. Capacity: 3 litres/side. Working at: 2.0 bar.	

This report details a visual inspection relating to the potential capability of the equipment, not for compliance with any regulations unless specified above. (Please see covering letter for statement of compliance requirements).

Date of Inspection: 10 Mar 2016

Date of Last Inspection: 12 Mar 2015

Inspecting Engineer: Mr R Chambers

Date of Next Inspection: 10 Mar 2017

Signature:

Qualification: Engineer Surveyor







